



Michigan Lead Service Line Status


Data as of July 2023

GPCL*, Known, and Likely Lead Service Lines as a Percentage of Total Service Lines




*Galvanized pipes previously connected to lead plumbing (GPCL) are considered dangerous because galvanized pipes are prone to corrosion over time. This corrosion can result in lead leaching due to lead trapped in the corroded pipes, as well as direct lead leaching from galvanized pipes manufactured using certain processes.


Lead Service Line Status



10 Most Populous Counties



10 Counties with Highest Percentage Known or Suspected Lead Lines



Source: Department of Environment, Great Lakes, and Energy
SFA Staff Contact: Jonah Houtz, Fiscal Analyst

